Juvenile Detention Facility utilities plan view and description of the notes.

The pertinent notes are:

- 22. Double cleanout
- 23. Four (4) inch line attached to grease trap
- 49. Perimeter drain around the foundation. (This had previously, incorrectly, been described as a waterline during the pre-bid conference. It would still need to be repaired if it was hit but it wouldn't be as difficult.)



